POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT

REGION SITE NUMBER (to be assigned by Hq) _ A

NOTE: This form is completed for each potential hazardous waste site to help set priorities for site inspection. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections.

GENERAL INSTRUCTIONS: Complete Sections I and III through X as completely as possible before Section II (Preliminary Assessment). File this form in the Regional Hazardous Waste Log File and submit a copy to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Task Force (EN-335); 401 M St., SW; Washington, DC 20460. I. SITE IDENTIFICATION A. SITE NAME DELTA B. STREET (or other identifier) WORKS IRON BLVD, INDUSTRIAL E. ZIP CODE C. CITY D. STATE 0360 HOUMA TERREBONNE G. OWNER/OPERATOR (if known) 2. TELEPHONE NUMBER H. TYPE OF OWNERSHIP 1. FEDERAL 2. STATE 3. COUNTY 4. MUNICIPAL 5. PRIVATE 6. UNKNOWN I. SITE DESCRIPTION J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) K. DATE IDENTIFIED (mo., day, & yr.) L. PRINCIPAL STATE CONTACT 504-342-1227 HUGHES BILL II. PRELIMINARY ASSESSMENT (complete this section last) A. APPARENT SERIOUSNESS OF PROBLEM 1. HIGH 2. MEDIUM 3. LOW 4. NONE 5. UNKNOWN B. RECOMMENDATION 1. NO ACTION NEEDED (no hazard) 2. IMMEDIATE SITE INSPECTION NEEDED A. TENTATIVELY SCHEDULED FOR 3. SITE INSPECTION NEEDED b. WILL BE PERFORMED BY: A. TENTATIVELY SCHEDULED FOR: b. WILL BE PERFORMED BY: 4. SITE INSPECTION NEEDED (low priority) C. PREPARER INFORMATION 2. TELEPHONE NUMBER 1. NAME 3. DATE (mo., day, & yr.) III. SITE INFORMATION A. SITE STATUS 2. INACTIVE (Those sites which no longer receive 3. OTHER (specify):
(Those sites that include such incidents like "midnight dumping" where 1. ACTIVE (Those industrial or municipal sites which are being used for waste treatment, storage, or disposal wastes.) no regular or continuing use of the site for waste disposal has occurred.) on a continuing basis, even if infrequently.) B. IS GENERATOR ON SITE? 1. NO 2. YES (specify generator's four-digit SIC Code): C. AREA OF SITE (in acres) D. IF APPARENT SERIOUSNESS OF SITE IS HIGH, SPECIFY COORDINATES 1. LATITUDE (deg.-min.-sec.) 2. LONGITUDE (deg.-min.-sec.) E. ARE THERE BUILDINGS ON THE SITE? 9418078 2. YES (specify): 1. NO

T2070-2 (10-79)

Lages 243 Blank

Continue On Reverse

KIN. of Chimology Not unt tree os

1. COST CENTER		TECHNICAL DIRECTION DOCUMENT (TDD)			2.	
CENTER		UNCONTROLLED HAZARDOUS WASTE SITE PROJECT			No. F-6-8101-27	
EP152-6 ecology and environment, inc.						
3.	Priority:	4. Authorized	5. EPA Site	6. Completion D	Pate:	7. Reference Info:
	☐ High	Overtime	Identification			Yes No
	Medium	1	Number			Attached
	Low	☐ Yes ☐No	LA01317	3-31-8	<u> </u>	☐ Pick Up
8.	General Task Description: Conduct reconnaissance inspection at Delta Iron works, Industrial Blud. In thouma, Louisiana. Collect samples of any runoff/leachate from site.					
9.	Specific Elements: FIT representative must: - notify appropriate state agencies f - decility representative - complete PA - complete T2070-3 with applicable. Supplemental forms if necessary - indicate necessity t priority of M-site sampling the spection of suggest locations for sampling - photograph to document site conditions - immediately notify DPC of 0311 Violations					
11.	Desired Report Form: Formal Report Letter Report Formal Briefing					
	Other (Specify):					
12.	2. COMMENTS:					
13.	Authorizan	ulub.	Jayda gnature)		14.	Date: 1/15/81
15.	Received B	y: XAccepted [Accepted with except	ions Rejected	16.	Date: 1/15/81

Sheet 1 Sheet 2 Sheet 3 Sheet 4 White — FITL Copy
Canary — DPO Copy
Pink — Contracting Officer's Copy (Washington, D. C.)
Goldenrod — Project Officer's Copy (Washington, D. C.)
Photocopy to E & E NPM (Washington, D. C.)